

REPORT of SURVEY for REPAIRS, &c.

No. 8465 Date of Writing Report 188 Port of Glasgow Received in London Office, 10 APR 88
 No. in Reg. Book. Survey held at Glasgow Date, First Survey 22nd March Last Survey 12th April 1888
 600 on the Iron S.S. "Amrapoora" Master Curran

TONNAGE: NET 1619 GROSS 2464 UNDER DK. 9427
 Built at Greenock By whom Scott & Co When 1874
 Owners Brit & Burmese S. & C. Co (Lim) Port belonging to Glasgow
 Owner's Address Glasgow
 If Surveyed Afloat or in Dry Dock Afloat Name of Dock Queen's Destined Voyage Rangoon
 Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.
 (If these particulars are not yet recorded in the Register Book.)

Last Survey, No. 8230 Port Glasgow Classed S.S. 26th Dec 83 100 A 1 11.87
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) as painted on Ship } in Summer ft. ins. }
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case. } in Winter ft. ins. }

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of S.S. No 3 Lm C 11/87
 The after cross bunker cleared. After the ceiling removed the Plating. Frames re chipped, oarped repainted. Some of the close ceiling in Bunker. Parts of the plating at bottom of several ribs & parts of horizontal & vertical stiffening angles to Bunkers & angles to one Beam renewed. The Floors Coated with Cement wash. Part of the close ceiling in Bunker renewed remainder replaced
 On main D^c at sides of E & B. Hway. had plates on Port side & one on Starboard with 1100 ft 3 1/2 pitch pine deck flat renewed

PRESENT CONDITION OF THE		Plating & Counter		Ceiling		Boats	
Decks	food	Plank (Bottom) & Counter	food	Rudder	food	Masts, Yards, &c.	food
Waterways	"	Transoms or Rivets	"	Windlass & Capstan	"	Condition, how ascertained	By name
Comings	"	Breasthooks and Stemson	"	Pumps	"	Sails	food
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Cement (If Iron Ship)	"	Anchors	No. of 3 B. 10. 24.
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the opening	"	Caulking of Bot'm, D'k, & Watrways	"	Cables	"
Planksheers	"	Ditto ditto at other places	"	Copper, or Y.M. (State if on Felt.)	"	Hawsers & Warps	"
Sheerstrakes	"	Keelsons	"	When put on	"	Standing & Running Rigging	"
Topsides	"	Clamps & Shells	"		"	Hatches	"
Wales	"		"		"		"
Engine Room Skylights	"	Coal Bunker, Openings, Lids, &c.	food	Scuppers	food	Cargo & Main Hatchways	food

General Observations, Opinion as to Class, Recommendation, &c.:
 The requirements of S. O. No 3 being now completed and vessel placed in food condition I respectfully beg to recommend her as being in my opinion eligible to retain her class & to have record entered S. O. No 3 in Reg Book

Entry Fee (if chargeable) per Scale I., Sec. 27... £ 5 : - : -
 Office Fee (if chargeable) per Scale II., Sec. 27... £ : - : -
 Survey Fee (per Section 28) £ 2 : 2 : -
 Special on Damage, Fee (if any) (per Sec. 28).... £ : - : -
 *Certificate (if required) to be sent as per margin £ : - : -
 Travelling Expenses (if chargeable) £ : - : -
 Second Surveyor's Fee (if any) £ : - : -
 Committee's Minute
 Character assigned 100 A 1
 TUES 17 APRIL 1888
 Fees applied for, 10/4/ 1888
 Received by me, [Signature]
 Surveyor to Lloyd's Register of British & Foreign Shipping.
 S.S. No 3 - 2786