

Report of Survey for Repairs, &c., of Engines and Boilers.

THURS. 7 JAN 1892

No. 11208 Date of Writing Report 4th January 1892 Port of Glasgow
 No. in Reg. Book 579 Survey held at Glasgow, City of Cambridge Master J. Black
 Date, first Survey 1st Dec. Last Survey 30th Dec. 1891
 No. of Visits 4
 Tonnage Gross 3788 Net 2443 Vessel built at Belfast By whom Workman Clark & Co. When 1882 Boilers, when made (Main) 1882 (Donkey) 1882
 Registered Horse Power 600 Engines made at Glasgow Owners J. Smith & Sons Port Glasgow Voyage Indian
 No. of Main Boilers Three Steam Pressure 80 lbs in Main Boilers 80 lbs in Donkey Boiler 50 lbs
 H Surveyed Afloat or in Dry Dock Queens (State name of Dock.)
 Class of Vessel & Machinery 100A1
 (As in Register Book, including dates of Special Surveys of Ship and of last Boiler Survey.)
 Last Survey No. 10932 Port Glasgow

Particulars of Examination and Repairs (if any) Annual Boiler
 (State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs.) Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *yes*
 Do " " Donkey " " " " " " *yes*
 If this was not done, state for what reasons? *✓*
 And what parts of the Boilers could not be thus thoroughly examined? *✓*
 Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each boiler? *✓*
 Did the Surveyor examine the Safety Valves of the Main Boiler? *yes*
 At what pressure were they afterwards adjusted under steam? *80 lbs*
 Did the Surveyor examine the Safety Valves of Donkey Boiler? *yes*
 To what pressure were they afterwards adjusted? *50 lbs*

The cylinders, slide-valves, pumps, cranks and tunnel shafting-including thrust shaft-and pistons, opened out for survey, and found in good condition
 The main boilers and mountings, also examined, and found in good order throughout. Steam raised in these boilers, and the safety valves tested to the working pressure.
 The donkey boiler and mountings examined and found in good order; afterwards steam raised and the safety valves tested to working pressure.
 The sea-connections and propeller shaft, were examined in Sept. 1891

General Observations, Opinion, and Recommendation:— This vessel's machinery is now in safe working condition, and in my opinion, is eligible to remain as classed, and to have notification **L.M.C. 9.91**
 (State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 1,89, B.&M.S. 1,89, or L.M.C. 1,89, as the case may be.)

Office or Registration Fee (per Sec. 27) £ : : Fees applied for 5/11 1892
 Survey Fee (per Section 28) £ 2.10.4
 Special Damage Fee (per Section 28) £ : :
 Travelling Expenses (if chargeable) £ : :
 Received by me, R. J. B. ...
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

* State if Certificate is required.
 Committee's Minute FRI 8 JAN 1892 TUES. 12 JAN 1892
 Assigned + L.M.C. 9.91
 BS 12, 91
 Referred to the G.B.

16-L.R.F.H.-Form No. 9.—Transfer to the Registrar of Shipping and Machinery (The Surveyors are requested not to write on or before the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

GLS 164-0027

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

11208 GLO

It is submitted that this

vessel is eligible to

have + L.M.C. 9-9/1 + B.S. 12-91

recorded.

General Form 14th Jan'y 1892

N.A.

Notation of X L.M.C. 9.9.1

7-1-92

only may be made

See letter from Owners

re. to the propriety of

owners A/S

B.S. in the Register Book

N.A.

11-1-92



© 2019

Lloyd's Register Foundation

THE SURVEYORS ARE ADVISED THAT TO WRITE AND THIS M...