

Do. of Houses on Deck 465.45
Do. of excess of Hatchways 117.27
Do. above Crown of Engine Room ..

Length on deck from fore part of stem to after part of sternpost
Longitudinal Number

473 ✓

When built 1915
By whom built Wm. a
Federal

43134

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.

2nd December 1915.

Dear Sirs,

I beg to acknowledge the receipt of your letter of the 30th ultimo from which I note that the space immediately under the Shelter Deck of the steamer "CUMBERLAND" (Messrs. W. Hamilton & Co's No. 299) has not been provided with cargo battens because you contemplate continuing the insulation in this space at an early date.

In the circumstances it will be necessary for the notation:- "Cargo battens not fitted in upper tween decks" to be made on the certificate of classification and in the Register Book, but this notation will of course be removed as soon as the insulation of the upper tween decks is completed.

The Society's Surveyors at Greenock are being duly advised of your intentions in the matter.

I am, Dear Sirs,

Yours faithfully,

Assistant to the Secretary.

Messrs. The Federal Steam Navigation Co. Ltd.,

2 Fenchurch Avenue, E.C.



© 2019

Lloyd's Register
Foundation

Brought for record 30 .. 6