

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18 When handed in at Local Office 18

Port of

Glasgow

No. in
Reg. Book.

Survey held at

Glasgow

Date, First Survey

and

Last Survey 22 Nov. 1899.

(No. of Visits)

Master

YEAR.

MONTH.

TONNAGE:-

Built at

Lumbarton

By whom

W. Denny & Bros.

When

1894

9

GROSS 5049

Owners

Henderson Bros. (Anchor Line)

Port belonging to

Glasgow

UNDER DEK 4131

Owners' Address

(if not already recorded in Appendix to Register Book.)

NET 3192

Surveyed Afloat or in Dry Dock?

By

Name of Dock

Goran

Destined Voyage

New York

WB=CellDBorDBa

92 feet; uE&B

64 feet; f

156 feet;

total capacity 63 tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.Years
A
not
expired.Machinery and Boiler
Surveys
(including date of N.B., if any).

+ 100 AI

+ LMC 5.99

5.99

SS. Lon No. 3-8.96

Society's Freeboard (if assigned) as
painted on Ship and now verified

Last Report, No. 48138

Port

Lir

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Docking

Bottom cleaned, examined and recoated.
The owner's representative Mr. McNeill Reid, informed us that the owners did not intend to keep the vessel classed in this Society, and that a letter would be sent to that effect; this letter however has not yet been received.

SUMMARY OF DAMAGE REPAIRS:-

Renewed ...

Removed and Faird or Repaired ...

Faird or Repaired in place ...

Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:-

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Waterways

Coamings

Beams & Fastenings

Outside Plating

Caulking of ditto

Rivets

Breasthooks & Crutches

Transoms

Frames

Reverse Frames

Floors

Keelsons

Stringers

Inner Bottom Plating

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

(State which.)

Rudder

Windlasses

Have Pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Dblg. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Treenails

Breasthooks & Stemson

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shelf

Salting (State if examined.)

Copper, or I.M. (State if on Feet.)

When put on, Month

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

" length (on board)

" Rule length (per Table 22)

Hawsers & Warps

Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptnD98, &c."

The above is sent for the information of the Committee.

Office Fee (if chargeable) per Scale II., Sec. 27

Survey Fee (per Section 25)

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for,

18

Received by me,

18

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRI. 8 DEC 1899

No action till BS becomes due in May next
when inquiry is to be made of owners

GLS186-0067

WED. 8 JUN 1900

Withdrawing Class

see. ^{to insert}
Write down 24/6/00.
" 24/6/00.

from 14 June, 1900
Decision of Classing
Once confirmed A.D.



© 2019

Lloyd's Register
Foundation

N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.