

No. 1168.

(Received in London Office,

TESTS OF BOILER STEEL.

Tests of 1 Steel Plate manufactured by Messrs. J. W. Beardmore of Parkhead, Glasgow
for Boiler No. 280/1/2 to be constructed by Messrs. J. W. Edder & Co. of Glasgow
for Messrs. J. W. Edder & Co. P.S. No. 280/1/2

Date first visit 20/8/83 last visit 20/8/83 No. of Visits 1

The Plate specified in the accompanying copy of Advice Notes ^{are} were rolled from 1 charge. The tensile test has been applied to 1 sample as set forth below, and the temper and bending tests to a shearing from the plate with satisfactory result.

[illegible]

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

Fee £ : :

Expenses £ : :

£ : :

To be paid by

Messrs. J. W. Beaman

Surveyor, Lloyd's Register.

© 2021

*M
Lloyd*



© 2021

Lloyd's Register
Foundation