

No. 1316

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received in London Office.

## TESTS OF BOILER STEEL.

Tests of 4 Steel Plates manufactured by Messrs. J. W. Beardmore of Parkhead, Glasgow  
for Boiler No. 104 to be constructed by J. & J. Thomson of Glasgow  
for Messrs. G. Connell & Co's. S.P. No 187

Date first visit 12/10/86 last visit 15/10/88 No. of Visits 2

The Plates specified in the accompanying copy of Advice Notes were rolled from ✓ charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests to a shearing from each plate with satisfactory results.

[illegible]

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

*Fee* ..... £       :       :

*Expenses* £       :       :

£ : :

To be paid by Messrs. J. W. Beardmore

*Surveyor, Lloyd's Register.*

Glasgow

16/10/83



J. & J. Thomson's No. 104.  
Borden 104



© 2021

Lloyd's Register  
Foundation