

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received in London Office,



Tests of 12 Steel bars manufactured by Messrs J. W. Beardmore of Parkhead  
for Boiler No. 292 & 293 to be constructed by " W. Denny & Co of Dumbarton  
for No 294 vessel building by " " " " " "

Date first visit Jan 30<sup>th</sup> last visit Feb 11<sup>th</sup>/85 No. of Visits 2

The Steel Stays specified in the accompanying copy of Advice Notes were rolled from One charges. The tensile test has been applied to 2 samples as set forth below, and the temper and bending tests proved satisfactory.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	<sup>dia</sup> 2 1/2 Long. Stays	13260	12	3	1.01	-	.801	22.4	24.9	22	
2	" " "	"	"	1	.99	-	.769	21.55	28	28	

*Expenses* £           :           :

£ : :

To be paid by Messrs. J. W. Beaumont & Co. 2/2/86

[6000—18/6/81.]

**R**

G

Lovers & W. Dean

© 2021

L Hindmarsh  
Surveyor, Lloyd's Register,

*S. S. S.*

When a second test is applied, the results should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

GLS202-0114