


Glasgow Report No 6990

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 157

(Received in London Office, 18 Dec 94)



TESTS OF BOILER STEEL.

Tests of *one* Steel *Plate* manufactured by *The Leeds Iron Co* of *Leeds*
 for Boiler No. *294* to be constructed by *A. Stephens & Son* of *Glasgow*
 for *Mr Stephens Yacht*

Date first visit *and* last visit *15 Dec. 94* No. of Visits *one*

The *one* specified in the accompanying copy of Advice Notes were rolled from
 charges. The tensile test has been applied to *one* samples as set forth below,
 and the temper and bending tests *have sample found satisfactory*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	Boiler front				1.04	1.00	1.04	26.50	25.4	28.12	

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by *The Leeds Iron Co*

J. B. Stevens
 Surveyor, Lloyd's Register,
at Hull

GCS202-0183