

S.S. Landaura Glasgow Report No. 4493.

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 2 680

(Received in London Office,



TESTS OF BOILER STEEL.

Tests of 10 Steel plates manufactured by Clydesdale Iron & Steel Co. of Mossend for Boiler No. 300 to be constructed by Denny & Co. of Dumbarton for S.S. No. 304 building by Wm Denny & Bro.

Date first visit 8th June last visit 11th June 1885 No. of Visits 2

The plates specified in the accompanying copy of Advice Notes were rolled from charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests to a sample from each plate all of which proved satisfactory.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	10'-5" x 54 1/2" x 3/16"	D220	✓	6431	5.25	1.24	6.66	18.4	28	30	

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by Manufacturers Glasgow

© 2021 J.P. 17/6/85
 J. Thomson
 Surveyor, Lloyd's Register
 Foundation
 13/6/85