



No. 4614

TESTS OF BOILER STEEL.

Tests of 2 Steel Plates manufactured by The Steel Co. of Scotland of Bochain for Boiler No. 125 to be constructed by Messrs J. & F. Thompson of Glasgow for S.S. No. 134 building by Aitken & Mansell

Date first visit 9th April last visit ✓ No. of visits 1

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 2 samples as set forth below, and the temper and bending tests Satisfactory

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	Furnace Front	G.88	1098	745	1.19	887	25.7	28.9	22.5		
	BK. Tube	C.94	903	875	1.23	1076	30.95	28.7	23		

JP
18/4/87

Fee £ : :

Expenses £ : :

£ : :

To be paid by _____



© 2021

J. Roberts
Surveyor, Lloyd's Register
Glasgow
1/3/4/87