

No. 6918

(Received at London Office,

TESTS OF BOILER STEEL.

Tests of 3 Steel plates manufactured by *The Steel Co. of Scotland of Blochairn*
 for Boiler No. 232 to be constructed by *Messrs. Nelson & Co. of Glasgow*
 for the S. S. No. 14 Building by *S. W. Knight & Co.*

Date first visit *6/3/88* last visit *16/3/88* No. of visits



The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to / samples as set forth below, and the temper and bending tests *Satisfactory*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	<i>Straps 1"</i>	<i>Stock</i>		<i>3363</i>	<i>1.00</i>	<i>1.24</i>	<i>1.24</i>	<i>35.75</i>	<i>28.8</i>	<i>24</i>	

D.P. 20/3/88

Fee £ : :
 Expenses £ : :
 £ : : _____

To be paid by _____

J. J. Roberts
 Surveyor, Lloyd's Register
 Glasgow
16/3/88