

Reference

In
4 Enclos.

Lloyd's Register of British
and Foreign Shipping.

36. Oswald Street, Glasgow.

14th Jan'y 1891

The Secretary
Sir London.

In reply to your letter of yesterday's date respecting the "Boothiae" I beg to state that in consequence of damage stated to have been caused by cargo shifting the main deck flat is now nearly partly removed for renewal whereby it will be rendered practicable to fit rider plates to the beams in way of the web frames - the after one alone excepted.

The size of the main deck beams is $8\frac{1}{2} \times 8\frac{1}{16}$ amidships to $9 \times 7\frac{1}{16}$ at ends as now shown on sketch.

Yours truly
J. Daukins
Lloyd's Register Foundation

Referred to the Chief Surveyor.

W.H.

15.1.91

S.S. Borghese

It is submitted that provided
a rider plate be fitted to the
beams in way of the webframes
as suggested by the Surveyor, the
webframes & side stringers be as
proposed, and the work be carried
out to the Surveyor's satisfaction
the same will merit the approval
of the Committee.

Lri 14.1.91

Airs. 15th

3 plans

1st Entry reft.

10/2021 J.W.

157 11/91

ANSR
REC'D. 15 JAN 91
LONDON.
LLYDS' REGISTER,

Lloyd's Register
Foundation