

S.E. Howarden Castle

It is submitted that this report be returned to the Surveyors at Glasgow with the request that it should be completed by filling up the blanks for the sizes of the pumps, the areas of safety valves and the working pressures for the screwed shafts, and also to state the effective diameters of the screwed shafts. They should also be requested to return the approved tracing unless it is still in use.

C.E.S.

15.7.91.

Ltr. to Gf. 15.7.91.



© 2021

Lloyd's Register
Foundation

GLS223-0202