

Sent to Chief Surveyor 21.3.96

Received from Chief Surveyor _____

VESSEL'S NAME Im Bh Orthos Report gls No. 14299

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

DAMAGE AND S.S. No. 1 (due 5.94)Damage through Groundingnow repaired as follows:- Vessel placed in dry dock

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Faired or repaired							

Other items:- and minor repairs effectedThe S.S. No. 1 has also been held and following repairs done:--

Fore topgallant mast, and fore topgallant-yard renewed
and minor repairs

It is submitted the vessel is worthy to remain classed 100 A Iwith record of Survey 3.96 gls and notation of

S.S. gls N° 1. 96 as recommended.

100 A I3.96 glsS.S. gls N° 1. 96

© 2021
 Lloyd's Register
 Foundation

GLS253-0031