

and a copy of the
Circular and
all other papers of the
same character will be ready
for examination and report made
about the same time. The
Circular will be forwarded
to you by the earliest
opportunity.

Very truly yours &c &c
John Angus "Gordon" was the
skipper who was dying in the steerage
deck sleeping in his cabin
and in his cabin they will be found
day books, & accounts of money
received before his arrival
from various ports of call
and from his crew
in his cabin, will be found
a quantity of paper. One piece of lead
will suffice and broken, four pieces
one stanchion end each, badly bent
and closed for sheet stanchions etc
and twisted. The remaining of the
circular board twisted, one part in
fairlead broken, one length of
maple branching broken, one part



one hundred and forty fathoms of gun
and a half inch iron riveted chain.
The compass did - two pieces of curved iron
rail about fifteen p. l. to be removed.
four clamps with which to be repaired,
repolished and reattached; wood
chuck for wheel braces to be renewed.
paper covering board to be replaced. one
cubic iron fastened to the windlass, about
hundred feet of propeller shafting to be
removed & the top part of four and a half
inch diameter chain to be replaced. the
cabin lining (in way of bolt fastenings)
of wood also removed & upon applica-
ble replaced. This accommodation
being made it may be placed in
as good and efficient condition as
the most perfect escape was obtained
by examination of the Albion.

In Sect. that made bottom took
Lfs 150 of Rubber ~~in 450~~ no damage to hull
fibers of paper - one piece of lead
chain split and broken; four polished
iron clamps and wood badly rot-
tened chuck for wheel braces re-
placed and the covering of paper
covering board replaced and
fastened the same and built up pro-
perly. Total cost £100.



© 2021

00332/2