

F.E.

Received by Chief Surveyor

20/8/96.

Received from Chief Surveyor

VESSEL'S NAME

H.S.S. La Plata

Report

46

No. 14620

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Items.	Additions (if any) required by Rules.	On account of:—
Main Sheerstrake . .	3/20	{ 2/10 Proportions 1/20 Erections
Spar Sheerstrake . .		
Description of Framing:— Ordinary. Deep framing in No. 2 Hold. (viz., ordinary, deep, zed, channel or bulb-angle).		

only.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ 100 A.1. ("Heel") as recommended.

+ 100 A.1. ("Heel")

2 Dks (1pt Hl - W.S. & U. Hl - Teak 3.) 3 tr. B.

W.B. = Pull D.B. a 68' u.E. & B. 74' f 140' 560t, F.P.T. 43t, A.P.T. 14t.

B.K. 9" Perm.

20/8/96.



© 2021

Lloyd's Register
Foundation

GLS256-0050