

Received by Chief Surveyor

26/9/98

Received from Chief Surveyor

1

VESSEL'S NAME

In. S.S. Chollerton

Report

Gls.

No.

16414

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE.

Damage through

fire per Karachi Report-27; and stress of weather.

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....						1	4
Removed and faired or repaired.....							2
Faired or repaired in place.....							

Other items:-

Main deck in way of storerooms doubled  
Sheathing on Spar deck renewed in way of repairs  
Engine room store room bulkhead faired  
and a few deck fittings renewed or made  
good as required and one bow rising plate  
renewed.

It is submitted the vessel is worthy to remain classed

with

record of Survey

9.98

as recommended.

100 A.1.

Spar Deck.

9.98 Gls.



© 2021

Lloyd's Register

Foundation

GLS270-0015.1