

J. S. "Moskva"  
Rpt. 6.

Received at

Office.

189

# Lloyd's Register of British and Foreign Shipping.

(Report on Vessel No. 16439 Port Glasgow)

## No. 5843 SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Iron~~ Steel ~~Forgings~~ Castings, manufactured by Messrs. The Steel Coy. of Scotland Ltd. of Glasgow for the Vessel No. 307, being built by The Clydebank Sh. & Eng. Coy. of Clydebank have been inspected by me as set forth below, and found to be, so far as can be seen, sound and efficient

The words FORGINGS or CASTINGS, IRON or STEEL, should be struck out as may be required.

Mark on Forgings.

Lloyd's  
No. 5843  
R.W.

R. Wright

Glasgow, 16/8/97

	STERN FRAME.	RUDDER FRAME.	STEM.
Material*	<u>At Propeller Brackets</u> <u>Steel (Siemens Martin)</u>	/	/
How made	<u>Cast</u>		
Dimensions	<u>14" x 8"</u>		
Progress on Inspection	<u>—</u>		
Date when Inspected	<u>while in constant attendance</u>		


SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS, OR PARTICULARS OF TESTS APPLIED TO CASTINGS.

The above mentioned Castings have been subjected to hammering, tensile, and bend tests with satisfactory results. Owing to their peculiar form it was not considered advisable to subject them to a drop test.

	dia.	area	total	sq. in	"inches"
<u>Stern Frame</u>	<u>.84</u>	<u>.554</u>	<u>15.8</u>	<u>28.5</u>	<u>11% Best unfractured</u>
<u>Shaft Brackets</u>	<u>.76</u>	<u>.453</u>	<u>13.4</u>	<u>29.5</u>	<u>21% 100"</u>

Fee (if any chargeable) £ : :

To be paid at



Lloyd's Register  
Foundation

307

Stern frame  
Propeller brackets

6-20

||  
||

X

Handwritten notes and a diagonal line.

Handwritten notes and a diagonal line.

Vertical columns of handwritten notes and numbers.

