

S/S "Rostva"

With reference to the report received today from the Glasgow Surveyors, purporting to be a continuation of a previous report received on the 5th Inst and acted upon by the Committee on the 7th Inst, it is submitted that the Glasgow Surveyors be asked to explain why this supplemental report was not sent with the original report, and further to state why in view of there having been some defects discovered requiring repairs the first report received ^{made no reference thereto but} stated that on examination after the trial the engines were found to be in good order & safe working condition, ~~no reference~~.

~~Also in view of~~ to state why the certificates of class were apparently withheld some time & ultimately handed to the ~~owners~~ builders

~~It should be also stated that the copy of letter and the sketch referred to have not been received~~ (Since received 15th)

rr to gl
20/10/98

SLM
20/10/98
J.P.L.



© 2021

Lloyd's Register
Foundation

GLS270-0075