

14.1.03

to Chief Surveyors

13 1 03

Received from Chief Surveyors

SEL'S NAME

L.S. Ocampo

Report

J.S.

No.

18085

For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

Screw shaft

When due

The screw shaft was last examined in June 1900, and in reply to enquiry the Owners state the vessel is due to dock in about four months time when the shaft will again be drawn in for examination.

It is submitted this proposal might secure the favourable consideration of the Committee.



© 2019

Lloyd's Register  
Foundation

GLS288-0142