

Lloyd's Register of British & Foreign Shipping,

342, Argyle Street, Glasgow.

23rd October 1902

the Secretary
Glasgow
Sir

With reference to the Secretary's letter of the 22nd inst. respecting the steamer "Scamo" and enclosing letter received from the owners. I beg to state that the requirements of S. S. R. 3 were carried out in the bunkers and machinery space; with the exception of the drilling of the shell plating as required by the Rules. The drillings that were made at this part were on account of local deterioration in way of worn cement.

With regard to the survey in the holds, nearly the whole of the close ceiling was moved, the only part that was not disturbed were a few strakes at the bilge so that in order to complete the requirements

of the No 3 survey, the close ceiling at
the bilge should be removed also the
drilling of the strakes above the cement

I am, sir

Your obedient servant

St. Paul

P.S. The owners letter is enclosed
herewith :



© 2019

Lloyd's Register
Foundation

GLS288-0155 (2/2)