

No. 3811.

LLOYD'S REGISTER OF BRITISH AND FOREIGN



TESTS OF BOILER STEEL

Tests of // Steel *has* manufactured by *The Steel Co. of Scotland* of *Newton*
 for Boiler No. *295* to be constructed by *Messrs Blackwood & Gordon* of *Port Glasgow*
 for

Date first visit _____ last visit _____ No. of visits *constant attendance*

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to *2* samples as set forth below, and the temper and bending tests *from piece off each length proved satisfactory*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	<i>Rivet Steel</i>				<i>157</i>	<i>1" dia</i>	<i>.785</i>	<i>22.2</i>	<i>28.2</i>	<i>29.0</i>	
					<i>164</i>	<i>.99 dia</i>	<i>.769</i>	<i>21.7</i>	<i>28.2</i>	<i>28.0</i>	

W.P.
23/8/86

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by _____

© 2019

H. Hand
 Surveyor, Lloyd's Register,
Glasgow
 Foundation
19.8.86