

No. ... steamer "Nordstjernen"

The first entry report has been once returned to Mr. Padderatz in order that he might furnish further particulars, and he has now returned it but in some respects it is still incomplete.

The vessel appears to have been built in accordance with the Midship Section, submitted and approved for the 100 A Awning Decked Class, but the Surveyor has omitted to recommend her for this class at the end of the report. Also the Dimensions of Ship per Register are not given on the Report.

It is submitted that the vessel appears eligible to be classed 100 A. 1. Awning Decked with a load line of ~~14~~ 15 ft 6 ins.

~~Two Decks~~ "1st & Awning deck"

Three Tiers of Beams


C. C.B.C.

9/10/82

It is submitted that Mr. Padderatz should be requested to state the amount of freeboard to the Awning deck in addition to that given to the main deck, namely 1" 9" in his report.

C.

Report No 579 on Ship returned



© 2019

Lloyd's Register
Foundation

HAM 1116-0109