



BYRD & SON, Liverpool, London.

# POST OFFICE TELEGRAPHS.

No. of Message.....

If the accuracy of an Inland Telegram be doubted, the telegram will be repeated on payment of half the amount originally paid for its transmission, any fraction of 1d. less than  $\frac{1}{2}$ d. being reckoned as  $\frac{1}{2}$ d.; and if it be found that there was any inaccuracy, the amount paid for repetition will be refunded. Special conditions are applicable to the transmission of Foreign Telegrams.

Office Stamp

LOYD'S REGISTER

LONDON.

RECEIVED 18 SEP 91

Charges } £ s. d.  
to pay }


Handed in at the

ANSWER 18.

Office at

136d

Received here at



WEST HARTLEPOOL

TO {

Committee

Ldn

Q 58

185 ship we dont know  
whether your surveyor has explained  
the design of the engine  
room tank this has a  
fore and aft water tight division  
with four inch suction on

N.B.—This Form must accompany any inquiry made respecting this Telegram.



Lloyd's Register  
Foundation

PL 366-0029(114)



Chief Supervisor.

1899

U. S. - This is not necessary any inquiry made respecting this Telegram.

WEST HARTLEPOOL

WEST HARTLE POOL

ANSWER 18. Other at

REC'D 18 SEP 51

LONDON.


LANDS, REGISTER.

If the accuracy of an inland telegram be doubted, the telegram will be repeated on payment of half the amount.

POST OFFICE TELEGRAPHS

No. of message.

00000000







# POST OFFICE TELEGRAPHS.

No. of Message.....

Office Stamp.

STAR & SPOTTISWOODE, London.

If the accuracy of an Inland Telegram be doubted, the telegram will be repeated on payment of half the amount originally paid for its transmission, any fraction of 1d. less than  $\frac{1}{2}$ d. being reckoned as  $\frac{1}{2}$ d.; and if it be found that there was any inaccuracy, the amount paid for repetition will be refunded. Special conditions are applicable to the repetition of Foreign Telegrams.

Charges } £ s. d.  
to pay }



Handed in at the

WEST HARTLEPOOL

Office at

.M.

Received here at

TO { *Comme*

(2)

*each side and whole contents  
of tanks only amount to  
ninety tons we certainly thought  
that the two four inch  
centre suction would be sufficient  
to empty the tank*

N.B.—This Form must accompany any inquiry made respecting this Telegram.

© 2013  
Lloyd's Register  
Foundation

HPL 366-0029 (2/4).





STRA & SPOTTISWOODS, London

# POST OFFICE TELEGRAPHS.

No. of Message.....

Office Stamp.

If the accuracy of an Inland Telegram be doubted, the telegram will be repeated on payment of half the amount originally paid for its transmission, any fraction of 1d. less than  $\frac{1}{2}$ d. being reckoned as  $\frac{1}{2}$ d.; and if it be found that there was any inaccuracy, the amount paid for repetition will be refunded. Special conditions are applicable to the repetition of Foreign Telegrams.

Charges }  
to pay } £ s. d.



WEST HARTLEPOOL Office at

M. Received here at

Handed in at the

TO { Committee (3)  
this capacity on account of  
the peculiar dimensions of the  
ship 40 feet beam 18/3/4  
depth there is very little  
chance of the vessel taking  
a list. let us know

N.B.—This Form must accompany any inquiry made respecting this Telegram.

Lloyd's Register  
Foundation

HPL 366-0029(3/4)





WILL & SPOTTISWOODE, London.

# POST OFFICE TELEGRAPHS.

No. of Message.....

Office Stamp.

If the accuracy of an Inland Telegram be doubted, the telegram will be repeated on payment of half the amount originally paid for its transmission, any fraction of 1d. less than ½d. being reckoned as ½d.; and if it be found that there was any inaccuracy, the amount paid for repetition will be refunded. Special conditions are applicable to the repetition of Foreign Telegrams.

Charges }  
to pay }

£ s. d.



Handed in at the

WEST HARTLEPOOL

Office at

Received here at

TO {

by  
this  
to  
the  
on

*[Handwritten message, mostly illegible due to vertical lines and cursive script. Visible words include: "receipt", "necessary", "instructions", "now", "loading"]*

N.B. - This Form must accompany any inquiry made respecting this Telegram.

Lloyd's Register  
Foundation

HPL366-0029(4/4)



10

Messrs. Wither's No. 185.

It is submitted that the Builder should be informed that under the circumstances the arrangement of engine room suction is considered satisfactory, but that the suction required by the Committee must be fitted in the aftermost hold.

Tel. 18/9/91 W.A. G.B.  
Ans. 18th 10.9.91

& Conf. J.C. to H.C. Svr.

POST OFFICE TELEGRAPHS

No. of Message

Office Stamp



Lloyd's Register Foundation