

Sent to Chief Surveyor

1517-93

Received from Chief Surveyor

VESSEL'S NAME

CSS "Adjutant"

Report

Hpl No 9128

For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 31/5/92.)

Nature of Survey

When due

It is submitted that the Surveyor should be informed that the pumps should in all cases be tested.

J.H.L.

C. H. J.

17/7/93

See. to Hpl. 15/7/93



Lloyd's Register Foundation

HPL 370-0086

Inches in Ship.

in Sh