



APPROVED BY THE ADMIRALTY
FOR GOVERNMENT WORK.

LONDON OFFICE.
5 & 6, BILLITER AVENUE, E. C.

FURNESS, WITHY & CO., LIMITED,

WEST HARTLEPOOL.



16th April, 1894.

Lloyds Surveyors
West Hartlepool.

Dear Sirs,

204. S.S.

As desired enclosed we beg to hand you a small tracing of the lower deck stringers in connection with the spacing of beams. The pieces of face plate angle we have left off (marked in red) we contend are not necessary when the beams are so close together and are not required by your Rules.

For your information the new arrangement of framing and spacing of beams that we have given you has run out 5 tons heavier than the old arrangement. Against this we have saved 1 - 16 - 0 - 0 by spacing the web frames wider.

Yours truly,

For **FURNESS, WITHY & CO., LIMITED,**

C. W. S. Sewing
Shipyard Manager.



© 2020

Lloyd's Register
Foundation
HPL372-0117

1-2-4-0-9-2
17.4.92



© 2020

Lloyd's Register
Foundation

17.4.92

17.4.92