

28.9.99

Chief Surveyor

TELEPHONE G.P.O. No. 51.

S.

Lloyd's Register of British
and Foreign Shipping.

Dock Office Buildings, West Hartlepool.

LLOYD'S REGISTER
LONDON.

30th Sept^r 1899.

REC'D 2 OCT. 1899

ANSP.

Sir

In reply to the note, in your
passing letter of yest^{dy} date re-
"Manchester Corporation". I find
clerical error has been made
in writing the first entry Report
on that vessel and the thickness
upper deck stringer plate
should be 13/20" and that of the
bulkhead stiffeners 12/20".

I am Sir

Your obedient servant
C. B. Sweeney.

The Secretary.
London



© 2019

Lloyd's Register
Foundation

HPL386-0254

Referred to the Chief Surveyor.

[Handwritten signature]

Also for Mr. Hill to note.

- 2 OCT 1899

C. R. P.
2/10/99



© 2019

Lloyd's Register
Foundation

The
13/2
not
cgr