

F.E.

Received by Chief Surveyor 25.5.00

Received from Chief Surveyor

SSEL'S NAME Steel S.L. Marburg Report Apr No. 11185

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	$\frac{2}{20}$ "	proportions
Spar Sheerstrake . .		

Description of Framing:— Bulb angle as approved
 (viz., ordinary, deep, zed, channel or bulb-angle).

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \ddagger 100 A1 ("Steel") as recommended.

\ddagger 100 A1 ("Steel")
 2 Dks (Stl - Upt ws) 3 tr B.
 WB = Cell DB a & u @ 165' f 160' 888t FPT 89t APT 64t.
 FK. 6 BH. Cem. A & C P.
 P & B 268' 740'

S.H.T.
 C.H.P. 25/5/00



FRAMES, In Fore Body No. and spacing	bedth & thickness	Angle on ditto	Tie Plates	Deck Mat.
No. of Side Stringers				
FRAMES, In E. & P. Space				