

Ltr. to Hull 16/4/82.

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. _____

(Received in London Office, _____)

TESTS OF BOILER STEEL.

Tests of 10 Steel plates manufactured by *John Brown & Co. of Sheffield*
for Boiler No. *249* to be constructed by *Charles S^s Co. of Hull*
for No. *249* vessel

Date first visit *6th April* last visit *6th April* No. of Visits *one*

The *plates* specified in the accompanying copy of Advice Notes were rolled from *four* charges. The tensile test has been applied to *three* samples as set forth below, and the temper and bending tests *Six* samples

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
<i>1</i>	<i>End plates</i>	<i>139</i>	<i>4</i>	<i>2835</i>	<i>.67</i>	<i>1.4</i>	<i>.94</i>	<i>26.5</i>	<i>28.2</i>	<i>27</i>	
<i>2</i>	<i>"</i>	<i>127</i>	<i>1</i>	<i>2840</i>	<i>.68</i>	<i>1.4</i>	<i>.95</i>	<i>26.5</i>	<i>27.9</i>	<i>24</i>	
<i>3</i>	<i>"</i>	<i>126</i>	<i>3</i>	<i>2844</i>	<i>.68</i>	<i>1.4</i>	<i>.95</i>	<i>26</i>	<i>27.3</i>	<i>25</i>	

Fee £ 1 : 1 : 0

Expenses £ 1 : 11 : 0

Noted JAB £ 2 : 12 : 0

To be paid by _____

David Jones

Surveyor, Lloyd's Register,

London.

HU 395-0075

[6000 - 18/6/81]



© 2021

Lloyd's Register Foundation