

No. *10*

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

(Received in London Office,

TESTS OF BOILER STEEL.

Tests of *3* Steel plates manufactured by *John Brown & Co. of Sheffield*
 for Boiler No. _____ to be constructed by *Charles S. Cook of Hull*
 for *Dunbar boiler 260*

Date first visit _____ last visit *14 Dec* No. of Visits *1*

The *plates* specified in the accompanying copy of Advice Notes were rolled from
2 charges. The tensile test has been applied to *one* samples as set forth below,
 and the temper and bending tests *to each plate*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
<i>1</i>	<i>Boilers</i>	<i>4211</i>	<i>3</i>	<i>4716</i>	<i>.44</i>	<i>2.28</i>	<i>1.003</i>	<i>27.5</i>	<i>27.4</i>	<i>31</i>	<i>5.4 6.4 5.6 x 7/16</i>

Fee *J.B.* £ *✓* : *✓* : *✓*

Expenses £ *✓* : *✓* : *✓*

£ *✓* : *✓* : *✓* To be paid by _____



© 2020

David James
 Surveyor, Lloyd's Register,
 London

Lloyd's Register
 Foundation