

May 13<sup>th</sup> 1  
 Messrs Bailey & Leatham, Hull

For

Boiler No 91

July 27<sup>th</sup> 2 N'dale's steel plates

	17.5 <sup>1</sup> / <sub>2</sub> x 4.9 x 7 <sup>1</sup> / <sub>2</sub>
1	17.3 <sup>1</sup> / <sub>2</sub> x . . .
1	12.4 <sup>1</sup> / <sub>2</sub> x 4.4 x 2
2	9.10 <sup>1</sup> / <sub>2</sub> x 7.2 x 7 <sup>1</sup> / <sub>2</sub>
1	7.4 <sup>1</sup> / <sub>2</sub> x 5.4 <sup>1</sup> / <sub>2</sub> x .
2	5.9 x . . . 5 <sup>1</sup> / <sub>2</sub>
1	1.10 x 2.2 x 9 <sup>1</sup> / <sub>2</sub>
1	4.9 <sup>1</sup> / <sub>2</sub> thick x 7 <sup>1</sup> / <sub>2</sub>
1	5.6 x . . . 7 <sup>1</sup> / <sub>2</sub>
1	5.9 <sup>1</sup> / <sub>2</sub> x . . . 7 <sup>1</sup> / <sub>2</sub>
1	4.0 x . . . 7 <sup>1</sup> / <sub>2</sub>

bark

6065 D 6

6065 F

6065

6065 B

6065 L

6065 J T

6065 K

6065 G

6065

6065 J

6065 K

W.L.G. 88.  
 16.8.88.  
 LLOYD'S REGISTER OF  
 West Hartlepool  
 SHIPPING



© 2020

Lloyd's Register  
 Foundation

HVL401-0022