

F.E.

ed by Chief Surveyor 24/8/97

Received from Chief Surveyor

SEL'S NAME Iron Steamer "Indian Empire" Report Hul. No. 11259

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>2/16</u>	<u>Not required.</u>
Spar Sheerstrake . .	<u>✓</u>	<u>✓</u>
Description of Framing:— (viz., ordinary, deep, zed, channel or bulb-angle). <u>Ordinary.</u>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✱ 100 A.1. ("Iron") Steam Trawler as recommended.

✱ 100 A.1. ("Iron")
"Steam Trawler"

1. SK.

WB = M.T. 10' 5.7.

BK. 7½' Lem. 3 B.H.

gs

E. J. M.

24/8/97

© 2019



Lloyd's Register
Foundation

HVL414-0273

Brdth. & Thickness	Vessel.	Rule.	Size. Inches.	Spacing. Inches.
<u>✓</u>	<u>16ths or 20ths.</u>	<u>16ths or 20ths.</u>	<u>16ths or 20ths.</u>	<u>16ths or 20ths.</u>