

Hull Report No. 23510

Rpt. 14.

Port of HULL

7th March 1911.

REPORT ON MASTS, SPARS, AND RIGGING.

Gentlemen,

Having, in accordance with your instructions, examined the Masts, Spars, and Rigging, and Iron Work of same, of the

S. S. "FULMAR"

I have to report that I found the foremast dead-eye bolts defective, to be renewed; the mizzen chain plates to be cut off and bolt holes filled in also doubling plate to be put on in wake of mast wedges about three feet long. The masts etc with the exception of the above in good condition.

Fee £ 10 0

To the Surveyors, Lloyd's Register of British & Foreign Shipping,

Robt Martin



© 2020

Lloyd's Register Foundation