

1812

REPORT of SURVEY for REPAIRS.

Rev 20/1/59

No. 133745 Survey held at Liverpool Date Jan 4 15th 1859

on the Iron Barge Scout Master C. Johnson

Tonnage 285 Built at Liverpool When built 1855

By whom built Capt. H Owners Wm. H

Port belonging to Liverpool Destined Voyage

If Surveyed Afloat or in Dry Dock Dry Dock & Afloat

Last Survey, No. 14117 Port Liverpool Classed A I

REPAIRS Has been in the graving dock and the Bottom Scraped Clean and the ceiling inside taken up and the inner surface of the Plating and rivets exposed to view all of which appear good inside and out. The Plating coated with paint.

Present Condition of the

Decks	<u>good</u>	Trunnails		Windlass and Capstan	<u>good</u>
Waterways	<u>good</u>	Breasthooks and Stems	<u>good</u>	Pumps	<u>good</u>
Comings	<u>good</u>	Transoms, Pointers, and Crutches	<u>good</u>	Boats	<u>3 & 2 good</u>
Upper Deck Beams & Fastenings	<u>good</u>	Timbers of the Frame		Masts, Yards, &c.	<u>good</u>
Lower Deck Beams & Fastenings	<u>good</u>	Keelsons	<u>good</u>	Sails	<u>well found</u>
Planksheers	<u>good</u>	Clamps and Shelves	<u>good</u>	Anchors	No. of <u>3 Bussell & 1 Wedge</u>
Sheerstrakes		Ceiling		Cables	
Topsides	<u>all good</u>	Rudder	<u>good</u>	Hawsers and Warps	<u>all good</u>
Wales		Copper	When put on	Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. All Satisfactory

Is now in a fit and efficient state for the safe conveyance of dry and perishable cargoes to and from all parts of the world and in my opinion should retain her present character.

The Amount of Fee.....£ : : is received by me,

Special..... / : / : 18/1/59

Certificate (if required) , : 0 : "

Committee's Minute 21st January 1859

Character assigned



© 2019

Lloyd's Register Foundation

IRON433-0388

Contest. —

15545. —



© 2019

Lloyd's Register
Foundation