

1830

REPORT of SURVEY for REPAIRS.

Page 306. No. 7498 Survey held at Newcastle Date Nov 26th 1858
 on the Iron S.S. "Seaton" Master William Taylor
 Tonnage 552 Built at Newcastle When built 1854
 By whom built Palmer Bros. & Co Owners Nicholas Wood.
 Port belonging to London Destined Voyage London
 If Surveyed Afloat or in Dry Dock on Ship

Last Survey, No. 6779 Port Newcastle Classed 9 A1.
 REPAIRS 1264 Iron

Damage. — Done at this date. Renewed a large quantity of defective Rivets; straightened keel; caulked some leaky Butts and longitudinal beams of plating where necessary, and painted Bottom.

Present Condition of the

Decks	Good	Treenails	—	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson	—	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	—	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	Iron Good	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	"
Planksheers	"	Clamps and Shelves	"	Anchors No. of	3 B, 1 S, 1 K
Sheerstrakes	"	Ceiling	"	Cables	"
Topsides	"	Rudder	"	Hawsers and Warps	"
Wales	"	Copper	When put on	Standing & Running Rigging	"
Plank (Bottom) and Counter	"				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good.

Is now in good condition, fit to carry dry cargoes to and from all parts of the world, and is entitled to continue as classed.

The Amount of Fee.....£ 2 : 0 : 0 is received by me,

for Damage Special..... 2 : 2 : 0

Certificate (if required) " : " : "

Committee's Minute 11th February 1859

Character assigned

9 A1 record as per report



© 2019

Lloyd's Register Foundation

IRON433-0415