

REPORT of SURVEY for REPAIRS.

for Continuation.

No. 607 Survey held at London Date 6th 12th August 1859
 on the Iron Steamer "Follier" Master Jackson
 Tonnage 195 Built at Port Glasgow When built 1849
 By whom built J Reid & Co Owners Morris
 Port belonging to Greenock Destined Voyage London &
 If Surveyed Afloat or in Dry Dock Gilberts Gardeners Millwall

Last Survey, No. 15117 Port Iron Classed G A

REPAIRS in accordance with the rules for the Continuation of Iron Vessels Section 18

The vessel placed on the Gridiron the whole of the ceiling or lining inside removed (except in the range of the new work added in lengthening, at which part a portion of the ceiling was removed) the holds, coal bunkers, &c cleared, and the vessel in this state subjected to careful survey in strict accordance with the rules Sec 18 (Iron ships)

The oxidation scraped and beaten off the outside plating. When found to exist the butts of six of the side-ship plates on each side recaulked, and the bottom coated with red lead. The inner surface of the plating also scraped and cleaned.

Present Condition of the

Decks	<u>Good</u>	Tree-nails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>✓</u>	Breasthooks and Stems	<u>Good</u>	Pumps	<u>✓</u>
Comings	<u>✓</u>	Transoms, Pointers, and Crutches	<u>Good</u>	Boats	<u>✓</u>
Upper Deck Beams & Fastenings	<u>✓</u>	Timbers of the Frame	<u>Good</u>	Masts, Yards, &c.	<u>✓</u>
Lower Deck Beams & Fastenings	<u>✓</u>	Keelsons	<u>Good</u>	Sails	<u>Sufficient</u>
Plank-sheers	<u>✓</u>	Clamps and Shelves	<u>Good</u>	Anchors	No. of <u>3 13 15 16</u>
Trunks	<u>✓</u>	Ceiling	<u>Good</u>	Cables	<u>Sufficient</u>
Bottom (and Counter)	<u>Good</u>	Rudder	<u>Good</u>	Hawsers and Warps	<u>✓</u>
		Copper	<u>When put on</u>	Standing & Running Rigging	<u>✓</u>

Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

The vessel is now in good and efficient condition. It is in our opinion to be continued on the A 1 certificate for five years from 1858.

of Fee.....£ 2 : — : — is received by me,

Special..... 3 : 3 : —

Certificate (if required) : 2 : 6

Date 15th November 1859

Contd. 1 for 5 years from 1858.

W. S. Mumford
J. R. Ritchie

REPORT OF SURVEY FOR REPAIRS.

2009 Jan.

and cleaned and the ceiling replaced
the plankwork & waterways scraped examined and
found good

W. S. Mumford



© 2013

Lloyd's Register
Foundation