

# Continuation REPORT of SURVEY for REPAIRS.

No. 184 Survey held at London Date Aug 2<sup>nd</sup> to Sept 21<sup>st</sup> 1860  
 on the Screw Steamer "Gibraltar" Master R. G. Hall  
 Tonnage 983 Built at London When built 1834  
 By whom built 519 Owners Spanish & Portuguese Steam Co. Comp<sup>y</sup>  
 Port belonging to London Destined Voyage Gibraltar  
 If Surveyed Afloat or in Dry Dock Union Dry Dock & London Dock

Last Survey, No. 1722 Port Iron Classed A. 1.

REPAIRS Now done, the Rules Section 18 for Iron Ships Complied with, the outside of plating and the Planks, keels & Waterways scraped, Ceiling lifted in each Compartment, and the inside of plating, rivets and frames, beams, decks, Bulwarks, stringers, hoops, crutches and all other parts of the hull examined as far as practicable, the Windlass stripped examined and found good, the lining of the boiler renewed. Twenty three rivets renewed in the bottom under the boilers, their heads being worn. Her main and fore masts renewed and her bottom coated with paint.

Her Chain Cables have been changed, examined, and found good and suff<sup>y</sup>.

## Present Condition of the

Decks <u>good</u>	Treenails <u>None</u>	Windlass and Capstan
Waterways <u>Scraped, good</u>	Breasthooks and Stemson	Pumps
Comings <u>good</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Good and</u>
Lower Deck Beams & Fastenings <u>good</u>	Keelsons <u>Good</u>	Sails <u>suff<sup>y</sup></u>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes <u>Good</u>	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	When put on <u>None</u>
Plank (Bottom) and Counter <u>good</u>		Standing & Running Rigging

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

She is now in good and efficient condition, fit in our opinion to be continued for 3 years A. 1. from 1860.

B. W. Weymouth  
J. H. Ritchie

The Amount of Fee.....£ 5: - : is received by me,

Special.....4: 4: -

Certificate (if required)

Committee's Minute 5<sup>th</sup> October 1860

Character assigned Cont A 1

Cont A 1 for 3 years from 1860



© 2019

Lloyd's Register  
Foundation

IRON434-0354