

2599

2599

# REPORT of SURVEY for REPAIRS.

No. 17226 Survey held at Liverpool Date Oct 25 to Nov 7 1861  
 on the Syrian, New Stern (2m) Master Robert Jay  
 Tonnage 1492 Built at Belfast When built 1860  
 By whom built 1814 Owners Robt & Son  
 Port belonging to Liverpool Destined Voyage Mediterranean  
 If Surveyed Afloat or in Dry Dock in Dry Dock & Afloat

Last Survey, No. 2456 Port Iron Classed 12 A 1 6, 61

## REPAIRS

In consequence of damage has had the Propeller, an Iron taken off and replaced with New; And the Bottom has been coated.

## Present Condition of the

Decks	<u>Good</u>	Trunnails	<u>Direct</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	"	"	Sails	<u>well found</u>
Planksheers	"	Clamps and Shelves	"	"	Anchors	No. of 3 <u>brass</u> , <u>stream</u> & <u>large</u>
Sheerstrakes	"	Ceiling	"	"	Cables	<u>well found</u>
Topsides	"	Rudder	"	"	Hawsers and Warps	<u>well found</u>
Wales	"	Copper	When put on	"	Standing & Running Rigging	<u>Good</u>
Plank (Bottom) and Counter	"					

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Satisfactory

Is in an efficient state, fit for the conveyance of dry and perishable cargoes with safety, to and from all parts of the world, and in my opinion should be continued as classed.

The Amount of Fee.....£ " : " : " is received by me,

Special Damage 2' 2' - 1' 14/11/61  
 Certificate (if required) " : 5' "

Committee's Minute 19th November 1861

Character assigned 12 A 1



© 2019

Lloyd's Register  
Foundation

IRON435-0218



*"Syriary" 14226*



© 2019

Lloyd's Register  
Foundation