

# Changes of Owners 2622 ANNUAL SURVEYS.

Recd. 12/16/61

No. 2183 Survey held at Liverpool Date Oct 16 to 25 1861  
 on the Ron, B. Mosquito Master Hewitt  
 Tonnage 198 Built at Renfrew When built 1859  
 By whom built Henderson Owners Gamble  
 Port belonging to Liverpool Destined Voyage Buenos Ayres  
 If Surveyed Afloat or in Dry Dock in 42 Dwt afloat

Last Survey, No. 2183 Port of Iron Classed 9A 1/60

The present Condition of the

Decks  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers  
 Sheerstrakes  
 Topsides  
 Wales  
~~Plating~~  
 (Bottom) and Counter

~~Treenails~~  
 Breasthooks and Stemson  
 Transoms, Pointers, and Crutches  
~~Timbers of the Frame~~  
 Keelsons  
 Clamps and Shelves  
 Ceiling  
 Rudder  
~~Bottom~~  
~~Copper~~ cleaned 1600 When put on at present

<sup>Wash</sup> Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Sails Well found  
 Anchors No. of 2 Bow 1 Stern 1 Heavy  
 Cables Good  
 Hawser and Warps Good  
 Standing & Running Rigging Good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways All appear satisfactory

Appears in a condition for the safe conveyance of dry & perishable cargoes  
 to & from all parts of the world & recommends her to be continued as Classed the  
 ceiling from bulge to bulge has now been lifted & this part cemented from forward to aft  
 the whole of the plating rivets & frames good the inside plating above the bulge cleaned &  
 Committee's Minute 13th December 1861 painted

Character assigned 9A 1 M

IRON435-0242

Certificate (if required) Amn

Survey to £ 1. 1. 0. 1861  
 Changes of Owners 10-5 1861



Mosquito

"Reflect" 17216



© 2019

Lloyd's Register  
Foundation