

REPORT of SURVEY for REPAIRS.

2667

Rec 10/1/62

No. 1092 Survey held at Southampton Date January 9 18 62
 on the Iron Paddle Steamer "Pacific" Master W. H. Emmerton
 Tonnage 1469 Built at London When built 1854
 By whom built _____ Owners Arthur J. Clark
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock In dry dock

Last Survey, No. 1301 Port Iron Classed 9 A 1
57

REPAIRS

Both surfaces of the outside plating have been exposed to examination, in conformity with the Rules, and the rivets, butts and plating found satisfactory, except at the ends of the vessel inside, and a portion of the floors, which parts were found to be considerably oxidated. These parts were found to be considerably oxidated. These parts have now been scaled, and the surfaces of the plating scraped throughout. The inside surface has been painted with two coats of red lead, and the outside has received two coats of coal tar and naptha to the water line, and two coats of red lead from the water line to the gunwale.

Present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>6 in H.</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>6.</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frames <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>Well found</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B. 1 S. 2 H.</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>Complete</u>
Topsides <u>"</u>	Rudder <u>good</u>	Hawsers and Warps <u>Sufficient</u>
Wales <u>"</u>	Copper <u>When put on</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

This vessel is now in a good and efficient state of repair, fit for the conveyance of dry and perishable goods, and eligible, in my opinion to remain as claimed 9 A 1.

The Amount of Fee.....£ 2 : 0 : 0 is received by me,

Special..... 4 : 4 : 0

* Certificate (if required) : 5 : 0

Committee's Minute 10th January 18 62.

Character assigned 9 A 1
(H.S. 62)



© 2019

Lloyd's Register
Foundation

IRON 435-0264