

# REPORT of SURVEY for REPAIRS.

2827  
Change of Owners

No. 1766 Survey held at Swampoor Date June 18 1862  
 on the Non Iron Gladiato Master A Hora  
 Tonnage 591 Built at Stockton When built 1860  
 By whom built Pearcy Owners M. G. Klingender  
 Port belonging to London Destined Voyage Nassau  
 If Surveyed Afloat or in Dry Dock In G.D.

Last Survey, No. 2278 Port Iron Classed 9 A  
12.60

## REPAIRS

Has now been placed in the graving dock the bottom cleaned & coated

### Present Condition of the

Decks	} <u>Good as far as</u> <u>seen</u>	Breasthooks and Stemson	} <u>Good as far as</u> <u>seen</u>	Windlass and Capstan
Waterways		Transoms, Pointers, and Crutches		Pumps
Comings		Timber of the Frame		Boats
Upper Deck Beams & Fastenings		Keelsons		Masts, Yards, &c.
Lower Deck Beams & Fastenings		Clamps and Shelves		Sails <u>Well found</u>
Planksheers		Ceiling		Anchors No. of <u>3 Bow 1 Stern 2 Kedge</u>
Sheerstrakes		Rudder		Cables <u>Good</u>
Topsides		Bottom cleaned		Hausers and Warps <u>Good</u>
Wales		Copper & coats		Standing & Running Rigging <u>Good</u>
Plank (Bottom) and Counter		When put on <u>at present</u>		

### General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. All appear satisfactory

Appears in a condition for the safe conveyance of dry & perishable cargoes  
to & from all parts of the world & recommend her to continue as Classed

The Amount of Fee.....£ 1 : " : " is received by me,

Special..... " : " : " 2/6

Certificate (if required) " : " : " 5/6

Committee's Minute 1<sup>st</sup> July 1862

Character assigned 9 A



© 2019

Lloyd's Register  
Foundation  
IRON435-0449



*"Gladiator" 1766*



© 2019

Lloyd's Register  
Foundation