

REPORT of SURVEY for REPAIRS.

No. 258 on the Screw Steamer "William Hutt" Master Roberts
 Survey held at London Date July 22nd 18 62
 Tonnage 530 Built at Newcastle When built 1853
 By whom built Palmer Bros & Co Owners J. J. Collier Company
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Upper Globe Dock

Last Survey, No. 2176 Port London Classed 6 A1
 Cont 59 3 5. 69.

REPAIRS

Done at this date. ceiling all lifted
 Renewed about a thousand rivets in flat of bottom and counter, four lengths of deck of yellow pine re-painted inner surfaces of plating with red lead and linseed oil paint, re-painted outer surfaces of plating, bottom with two coats and upper works with one coat of paint and caulked a large proportion of Deck with Waterways and Stanchions.

Present Condition of the

Decks	<u>Good</u>	Greenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	"
Planksheers	"	Clamps and Shelves	"	Anchors No. of	"
Sheerstrakes	"	Ceiling	"	Cables	"
Topsides	"	Rudder	"	Hawsers and Warps	"
Wales	"	Copper	When put on	Standing & Running Rigging	"
Plank (Bottom) and Counter	"				
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good</u>				

Is now in good and efficient condition fit to carry dry and perishable cargoes to and from all parts of the world and is entitled to continue as classed & marked S.P.

The Amount of Fee.....£ 2 : - : - is received by me,

Special.....

Certificate (if required) : 5 : -

Committee's Minute 12th August 18 62

Character assigned Comp. 3

John Maxwell
Thos. M. Brown

© 2019

Lloyd's Register Foundation