

3172

REPORT of SURVEY for REPAIRS.

Rev 25/5/63

No. 3122 Survey held at Leith Date May 22nd 18 63
 on the Ship Summer Cloud Master Barnetson
 Tonnage 698 Built at Charlestown When built 1859
 By whom built Messrs. W. & J. H. & Co. Owners Messrs. Macgregor, Sinclair & Co.
 Port belonging to Leith Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 2170 Port Leith Classed 12 A 1
 60

REPAIRS

The whole of the ceiling has been removed, and all oxidation scraped or beaten off the inside and outside surfaces of plating. Frames &c. The cement in flat of bottom was found to be quite hard, and from thence upwards two coats of patent Varnish have been laid on. The outside has received four coats of metallic paint.

A portion of the deck amidships has been taken up, and relaid, and the main hatchways increased in width. - the fore and aft tie plates &c. being again efficiently connected.

Present Condition of the

Decks <u>Good</u>	Greenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>2 of Iron</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>3 in All</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frames at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Sails <u>Well found</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>3 Bower</u> <u>Stream Wedges</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>Complete</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>Good & Sufficient</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
Plating (Bottom) and Counter <u>"</u>	Copper <u>When put on</u>	

General Observations and Opinion,Caulking of Bottom, Deck, & Waterways. Good

This ship is in a good and efficient state of repair, fit for the conveyance of dry and perishable cargoes to and from all parts of the world, and eligible in my opinion to continue as classed 12 A 1.

The Amount of Fee.....£ 2 : 0 : 0 is received by me, Rev. MarshallSpecial..... 2 : 2 : 0Certificate (if required) 0 : 5 : 0£ 4 : 7 : 0Committee's Minute 26th May 18 63Character assigned 12 A 1

(T.S. 13.)



© 2019

Lloyd's Register
Foundation

IRON436-0309