

3946

# REPORT of SURVEY for REPAIRS.

Rec 17/1/65

No. in

Reg. Book.

No. 2410

Survey held at

Middlesbrough

Date

3<sup>rd</sup>

January

1865

on the

Screw Steamer "Elaine"

Master

J. B. Rose

Tonnage

393

Built at

Middlesbrough

When built

1864

By whom built

Candlish

Owners

G. Matthews & Co

Port belonging to

Sunderland

Destined Voyage

London & Mediterranean

If Surveyed Afloat or in Dry Dock

On R. Craggs & Sons Shipway & Afloat

Last Survey, No.

3711

Port

Swan.

Classed

A 1<sup>64</sup>

REPAIRS

Now done tops of waterballast tanks in after hold & for 17 ft. in fore do. connected to the outside shell plating with plates 20x7/16 Reverse bars being cut off & three plates fitted the same being connected to top of tanks & frames. Top of fore tank strengthened with two double angle iron bars from side to side 4x3x0/16, keel coated outside with paint.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Trunnails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good

Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the world & may in my opinion remain as now classed A 1

The Amount of Fee.....£ — : — : — is received by me,

J. P. Gladstone

Special.....3 : 3 : 0

Certificate (if required) : :

Committee's Minute 20<sup>th</sup> January 1865

Character assigned

A 1



© 2019

Lloyd's Register Foundation

IRON438-0101