

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 19256 Survey held at Liverpool Date Oct 31<sup>st</sup> 1864  
 on the S.S. "Behera" Master \_\_\_\_\_  
 Tonnage 1364 Built at Newcastle When built 1864  
 By whom built Marshall Bros Owners Shapple Dutton & Co  
 Port belonging to London Destined Voyage Mediterranean  
 If Surveyed Afloat or in Dry Dock in London graving docks

Last Survey, No. 3625 Port Iron Classed GA  
Spars Decked 64

## REPAIRS

Renewed a few rivets in Keel and flat of bottom and painted bottom with two coats of red lead and oil paint and one of McInnes's patent paint.

## Present Condition of the

Decks <u>Good</u>	Treenails <u>Rivets</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways "	Breasthooks and Stemson "	Pumps "
Comings "	Transoms, Pointers, and Crutches "	Boats "
Upper Deck Beams & Fastenings "	Timbers of the Frame at the openings "	Masts, Yards, &c. "
Lower Deck Beams & Fastenings "	Ditto Ditto at other places "	Sails "
Planksheers "	Keelsons "	Anchors No. of <u>30, 15, 20</u>
Sheerstrakes "	Clamps and Shelves "	Cables "
Topsides "	Ceiling "	Hawsers and Warps "
Wales "	Rudder "	Standing & Running Rigging "
Plank (Bottom) and Counter "	Copper <u>✓</u> When put on <u>✓</u>	

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. where seen Good

Is now in good and efficient condition and is in my opinion fit to remain as classed

The Amount of Fee.....£ " : " : " is received by me,

Special..... / : / : 0 3/3/65 Wm

Certificate (if required) " : " : "

Committee's Minute Liverpool 7<sup>th</sup> March, 1865

Character assigned See Report No 19257



© 2019

Lloyd's Register Foundation

LRON438-0158



*"Behera" 19256.*



© 2019

Lloyd's Register  
Foundation