

Half-time Survey - 2563 REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 173 Survey held at London Date April 4th 1865
on the Iron screw "Stawthorns" Master Driver
Tonnage 699 Built at Newcastle When built 1861
By whom built _____ Owners St Taylor
Port belonging to London Destined Voyage Newcastle
If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 2563 Port Iron Classed 6 A.1.

REPAIRS

Now done, a strake of feiling split out on each side in the flat and the man hole doors of the tanks off, the holds cleared, the outside surface of the bottom scraped and cleaned, and the windlass unhooking and stripped; the vessel examined throughout - the butts of the bottom plating caulked where necessary - the bulwarks ^{and staunches} in way of main rigging on the starboard side repaired - the waterway seam and the two next of deck, and the butts of the deck caulked - and the bottom plating painted.

Present Condition of the

Decks <u>butts caulked</u>	} <u>good</u>	Timberails <u>Rivets</u>	} <u>good</u>	Windlass and Capstan <u>stripped good</u>
Waterways <u>caulked</u>		Breasthooks and Stemson		Pumps
Comings	} <u>where</u>	Transoms, Pointers, and Crutches	} <u>good</u>	Boats
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.
Lower Deck Beams & Fastenings	} <u>seen</u>	Ditto Ditto at other places	} <u>and</u>	Sails
Planksheers <u>painted</u>		Keelsons		Anchors No. of
Sheerstrakes <u>do</u>	} <u>seen</u>	Clamps and Shelves	} <u>sufficient</u>	Cables
Topsides <u>do</u>		Ceiling		Hawsers and Warps
Wales <u>do</u>	} <u>seen</u>	Rudder	} <u>seen</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>painted</u>		Copper <u>Paint</u> When put on <u>now</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

She is now in good and efficient condition, fit in our opinion to remain as classed 6 A.1. and to be marked in the Register Book

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : 46

Certificate (if required)

Committee's Minute 19th May 18 65

Character assigned 6.12.1 (11.5.65) 6.12
Damage Fee £3.3.

© 2013
Lloyd's Register
Foundation

IRON438-0257