

Triennial Survey

REPORT of SURVEY for REPAIRS.

No. 30 Survey held at London Date Aug 21st & 22nd 1865
 on the Iron S.S. "Forcyra" Master T Goodwin
 Tonnage 794 Built at Stockton When built 1862
 By whom built 7637 Owners Ang. Ionian S N Coy
 Port belonging to London Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Youngs Dry Dock

Last Survey, No. 3882 Port Wm. Classed 9 A.1.
10, 64.

REPAIRS

now done, the bottom scraped and painted with
 Mc Killop's Patent — the hold cleared, limbers up-
 and planks of ceiling in each hold — Floors, Keelsons.
 Frames, Stringers, Beams, Ribs and plating examined
 and found to be in good condition —

Present Condition of the

Decks	} good	Ironails	} good	Windlass and Capstan
Waterways		Breasthooks and Stemson		Pumps
Comings		Transoms, Pointers, and Crutches		Boats
Upper Deck Beams & Fastenings	} where	Timbers of the Frame at the openings	} where	Masts, Yards, &c. <small>Condition, how ascertained,</small>
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails
Planksheers <u>painted</u>		Keelsons		Anchors No. of
Sheerstrakes <u>dr</u>	} seen	Clamps and Shelves	} efficient	Cables
Topsides <u>dr</u>		Ceiling		Hawsers and Warps
Wales <u>dr</u>		Rudder		Standing & Running Rigging
Plank (Bottom) and Counter <u>Scraped & painted</u>		Copper <u>Paint</u> When put on <u>now</u>		
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <u>good where seen</u>		

She is now in good and efficient condition
 fit in our opinion to remain as (Classed 9 A.1.)

The Amount of Fee.....£ : : is received by me,

Special..... 2 : 2 : 2

Certificate (if required) : 5 : —

Committee's Minute 13th October 1865

Character assigned 9 A.1.
(A.S. 65)

and to be marked in the
 Register Book t.s. 1865

B. Weymouth

Hornish

Lloyd's Register
 Foundation

IRON438-0487