

4353

REPORT of SURVEY for REPAIRS.

in Book. No. 2460 Survey held at West Hartlepool Date 31st Oct^r 1865
 on the S.S. "Admiral Eaton" Master J. Moor
 Tonnage 3110212 Built at Glasgow When built 1857
 By whom built _____ Owners M. H. L. & Co.
 Port belonging to West Hartlepool Destined Voyage Rotterdam
 If Surveyed Afloat or in Dry Dock Afloat in West Dock

Last Survey, No. 3428 Port Iron Classed 9 A 1 Iron

REPAIRS Boilers taken out repaired & replaced, being taken up in fore & main holds cement repaired where necessary ceiling relined with fresh new. Fore engine room bulkhead strengthened with extra angle iron bars. Decks caulked fore & aft.

Present Condition of the

ks
 erways
 ings
 er Deck Beams & Fastenings
 ver Deck Beams & Fastenings
 ankshaers
 erstrakes
 ppsides
 ales

Hulk (Bottom) and Counter

General Observations and Opinion,

Ironails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Caulking of Bottom, Deck, & Waterways.

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.
Condition, how ascertained.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in ^{our} opinion remain as now Classed 9 A 1

The Amount of Fee.....£ 1 : 0 : 0 is received by me,

Special..... : : -

Certificate (if required) : : -

Committee's Minute 7th November 1865Character assigned 9 A 1

© 2019

Lloyd's Register
Foundation

IRON438-0506