

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **33** No. **2420** Survey held at **Glasgow** Date **30th November 1865**
 on the **Chm. S. S. Napoli** Master **Livingstone**
 Tonnage **635** Built at **Glasgow** When built **1864**
 By whom built **486 Charles Cunell & Co** Owners **Handyside & Henderson**
 Port belonging to **Glasgow** Destined Voyage **Mediterranean**
 If Surveyed Afloat or in Dry Dock **Ed & McQuarrie Dry Dock**

Last Survey, No. **3896** Port **Iron.** Classed **A. 1.**

REPAIRS *Of Damage from Collision with S. S. "Beagle" New Stem, three Frames and Reverse Frames on each side, 14 plates on Starboard side and 13 plates on Port side, Wreath of Head and Head Rails, Bowsprit of Wood, Six Short Lengths of Cold Beam Stinger Bar, Wrought Heads of British Oak refitted and Bolts, Guard Rail and Chafing, Check to Forecastle repaired, Forecastle Deck Caulked*

The above Repairs of Damage are not to be Recorded in R. Book for request of the Owners

Present Condition of the

Decks	<i>Good</i>	<i>Nine</i>	<i>Good</i>	Windlass and Capstan	<i>Good</i>
Waterways	<i>do</i>	Breasthooks and Stemson	<i>do</i>	Pumps	<i>do</i>
Comings	<i>do</i>	Transoms, Painters, and Crutches	<i>do</i>	Boats	<i>do</i>
Upper Deck Beams & Fastenings	<i>do</i>	Timbers of the Frame at the openings	<i>do</i>	Masts, Yards, &c.	<i>do</i> from examination
Lower Deck Beams & Fastenings	<i>do</i>	Ditto Ditto at other places	<i>do</i>	Sails	<i>Good</i>
Planksheers	<i>do</i>	Keelsons	<i>do</i>	Anchors No. of <i>31 B. 1 Sh. 2 B. 2 Sh.</i>	
Sheerstrakes	<i>Chm</i>	Clamps and Shelves	<i>do</i>	Cables	<i>Complete</i>
Topsides	<i>do</i>	Ceiling	<i>do</i>	Hawsers and Warps	<i>do</i>
Vales	<i>do</i>	Rudder	<i>do</i>	Standing & Running Rigging	<i>do</i>
Plank (Bottom) and Counter	<i>do</i>	Copper	<i>When put on</i>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Ship in good Condition, Eligible in my opinion to remain as Classed

The Amount of Fee.....£ 2 : : is received by me,

Special..... 2 : 2 : ,

Certificate (if required) : : :

Committee's Minute **19th December 1865**

Character assigned

A 1

second damage repair

mk



© 2019

Lloyd's Register Foundation

IRON 439-0067