

4464

# REPORT of SURVEY for REPAIRS.

of Damage, also triennial survey

in Book. No. 19731 Survey held at Liverpool Date 25<sup>th</sup> Nov 16<sup>th</sup> Dec 1863  
on the Iron Screw Steamer "Hector" Master                       
Tonnage 1614 Built at Sunderland When built 1863-4 mo  
By whom built Young Owners Gosley  
Port belonging to Sunderland Destined Voyage Sir  
If Surveyed Afloat or in Dry Dock Under Gearing dock No 6

Survey, No. 3727 Port Liver Classed GA1  
IRS How done 7. 64

A large number of rivets in the keel, butts, and edges. A flat of bottom and lower part of bilges renewed, the wood siding from the bilges down, aloft and aft, lifted, and the cement renewed in the range of the damage. The ceiling laid, twelve frames on the starboard side, abreast of main hatch, between the main and gas deck stringers, set fair, repaired, and with the outside plating, thereat riveted the deck caulked also, the butts and seams the plating where requisite the bottom coated, and the plating inside cleaned and painted the back of the ender turned and retinned.

ways gs Deck Beams & Fastenings Deck Beams & Fastenings sheers trakes es (Bottom) and Counter	Good	Treenails	Good	Windlass and Capstan	Good	
		Breasthooks and Stemson		Pumps		Where
		Transoms, Pointers, and Crutches		Boats		Seen
		Timbers of the Frame at the openings		Masts, Yards, &c.	Good Where seen	
		Ditto Ditto at other places		Condition, how ascertained, from the deck	Good	
	Where	Keelsons	Where	Sails	Good	
		Clamps and Shelves		Anchors No. of	And	
		Ceiling		Cables	Sufficient	
		Rudder		Hawsers and Warps	Where	
		Copper		Standing & Running Rigging	Seen	
		When put on				

Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Good where examined

This ship is in good and efficient condition  
likely to remain as classed GA1 and to be  
ted in the Register book T.S. 65.

Amount of Fee.....£ 3 : " : is received by me,  
Special.....3 : 3 : - 2/166  
Certificate (if required) " : 5 : "

Committee's Minute Liverpool, 5<sup>th</sup> January, 1866  
Factor assigned GA1. Record Damage repairs  
(T.S. 65) GR

*[Signatures]*



"Hector" 1943/



© 2019

Lloyd's Register  
Foundation